







0105





v013
21.04.2023
K. M.
[cm]



vinci
play
















[cm]



vinci
play





[cm]



3,5h



vinci
play




0105 A
x1



0105 B
x1



0105 C
x1




0105 D
x1




0105 E
x1




011231
x1




011226
x1




012100
x1




011113
x2



011115
x1




012101
x1



994146
x1




011119
2x




011143
2x

K1,K2




p78
x2

K3




b219-2
x2

K2,K3



b231
x5







HPL





011230
x1

	HDPE	HPL	ST/INOX
2x	CE1	CL1	
1x	CE3	CL3	
1x	CE26	CL26	
1x	CE111	E93	
1x	CE112	CL112	
2x			E1
1x			E34 ^{K1,K3}
1x			E35 ^{K2}
			E37 ^{K2,K3}
1x			V001

	PLYWOOD	HPL
1x	PS8	PH8
1x	PS9	PH9
1x	PS19 ^{S1}	PH19 ^{S1}
1x	PS41 ^{S6}	PH41 ^{S6}
1x		PH56












[cm]







vinci
play





[cm]






vinci
play



PLYWOOD HPL
1x PS19 (S1) PH19
PLYWOOD HPL
1x PS41 (S6) PH41







HDPE HPL
1x CE112 CL112




[cm]




vinci
play



V001



[cm]



vinci
play