





# RB1492



v010  
17.03.2021  
A. P.  
[cm]





vinci  
play



[cm]



vinci  
play



[cm]




vinci  
play



vinci  
play









[cm]



[cm]



vinci  
play



[cm]




3h




vinci  
play




127116  
x6




052129  
x1




b66-5  
x4




b251-2  
x2




052127  
x1




R1




R2



R3









R5







R6


2x	E60
1x	E61
1x	E62
1x	E63
1x	E164 R1,R5
1x	E165 R2
1x	E168 R3
3x	12e017
1x	V001









3x 12e017




[cm]


vinci  
play





1x E62



2x E60




1x E61





[cm]



vinci  
play






1x E63




[cm]







vinci  
play






1x E164



1x E165










1x E168



[cm]

vinci play



[cm]

vinci  
play